





DRESSING TABLE ASCET



Assembly instruction

DRESSING TABLE ASCET


1024x431x782




G6 412.034 2	A11 3,5x16 28	B7 30x10 4	G13 4
C6 350 MM 2	B4 20	A16 60	A26 4x45 4
A3 20	C21 M6x10 4	C20 M6x10 4	G21 6 4
A13 3,5x30 8	A10 20	G34 600x425x30 2	G35 d10 l=1150 2
A5 4MM 1			

No	L x W	Q-ty
1	150x405	1
2	150x405	1
3	174x1018	1
4	1024x425	1
5	1024x429	1
6	150x405	1
7	350x100	2
8	350x100	2
9	457x346	2
10	429x100	2
11	429x100	1
12	508x144	1
13	508x144	1
14	429x100	1


1




2




3




4






5





6





7






8




9




10




11




12




13




14




15




16




17



18



19



20

